Technical and Detailed Guide to Cold Foil Printing

article · https://www.liangyufoil.com/docs/cold-foil-printing/

By Liangyu Laser Technical Team | Updated August 10, 2026 | 12-min read

Quick Answer: What Is Cold Foil Printing?

Cold Foil Printing is an inline metallic-decoration process that prints a UV-curable adhesive in the required image area, transfers foil onto that adhesive, then cures and rewinds the unused carrier. It is well suited to labels and packaging that need metallic effects, overprinting or production-speed efficiency, provided the substrate, adhesive, cure and press conditions are verified together.

Cold foil is not a universal replacement for hot foil stamping. It is a process choice. The right result depends on artwork, surface smoothness, foil grade, UV adhesive, curing energy, press configuration and the end-use requirements of the pack. This guide helps packaging buyers, label converters and press teams select, test and troubleshoot the process before a production order.

How Cold Foil Printing Works

Cold Foil Printing does not use a heated stamping die to release the foil. Instead, a printing plate applies adhesive where the metallic image is needed; the foil web is brought into contact with the wet adhesive, UV energy cures the adhesive, and the unused carrier is stripped away. The process is commonly integrated into offset or flexographic packaging and label workflows. An **industry cold-foil process reference from K Laser** shows the same adhesive, nip, curing and waste-rewind sequence.

Process stage	What happens	What to control
Adhesive imaging	UV adhesive is printed in the foil artwork area.	Plate quality, adhesive laydown, artwork detail and substrate cleanliness.

Process stage	What happens	What to control
Foil nip	The foil web contacts the adhesive-coated substrate.	Web tension, nip contact, alignment and foil grade.
UV curing	UV energy cures the adhesive through the foil system.	Lamp condition, dose, line speed and cure verification.
Carrier stripping	Unused foil remains on the carrier and rewinds.	Transfer completeness, clean edges, waste handling and roll tracking.
Overprint or protection	CMYK, varnish, laminate or another finish may follow.	Ink adhesion, visual effect and end-use resistance.



Technical and Detailed Guide to Cold Foil Printing 1

Cold Foil vs. Hot Foil: Choose by Job Conditions

Both processes create premium metallic decoration, but they solve different production problems. Do not select solely by a claim that one process is always faster, cheaper or more versatile. Run length, artwork, desired tactile effect, substrate surface, press configuration and finishing sequence should drive the decision. For a deeper comparison, see LiangyuFoil's **cold foil vs. hot foil guide**.

Decision factor	Cold foil is often a strong option when	Hot foil is often a strong option when

Production flow	The project benefits from inline application on a compatible press.	The design uses a separate finishing operation.
Artwork	Overprinting, tonal metallic effects, gradients or high-detail label artwork are required.	Sharp solid logos, tactile embossing or a classic premium stamp are the priority.
Tooling	The process can use a printing plate and adhesive image rather than a heated engraved die.	A heated die is already available or its effect is essential to the design.
Substrate	The surface is smooth enough and the adhesive system is proven by trial.	The selected foil grade and heat/pressure window are proven for the material.
Cost evaluation	Inline workflow, waste rate, plate cost and run length support the business case.	Die cost, offline handling and premium-effect requirement support the business case.

Labels and Packaging Application Matrix

Application	Why cold foil can fit	Test before approval
Narrow-web pressure-sensitive labels	Supports inline metallic decoration and subsequent overprinting.	Registration, adhesive transfer, web tension, varnish and rub resistance.
Wine and spirits labels	Can create metallic imagery and overprinted color effects on suitable label stocks.	Paper texture, fine detail, wet handling, scuff resistance and viewing-angle appearance.
Cosmetic cartons	Can add high-impact metallic areas in a packaging print sequence.	Coating type, UV adhesive, large-solid uniformity, rub and retail-light appearance.
Flexible packaging	May suit selected film constructions and high-volume visual effects.	Film type, surface treatment, migration/compliance requirements and laminate compatibility.
Promotional sleeves and cartons	Can support metallic graphics without a separate heated-die operation.	Score lines, abrasion, overprint adhesion and full-run consistency.

For foil selection and roll-format questions, start with LiangyuFoil's **cold stamping foil product page**. If the broader project compares decoration methods across labels and packaging, also review **foil printing for premium labels and packaging**.

Substrate, UV Adhesive and Cure Checklist

Cold foil quality is strongly linked to the printed adhesive image. Smooth coated materials can provide a more consistent surface than rough or highly absorbent stocks, but every commercial construction still needs a trial. Do not approve a foil based on a swatch alone when the production job uses a different coating, laminate, ink, film, additive package or curing setup.

- **Coated paper and paperboard:** Confirm coating type, gloss, absorbency, dust and print quality of the adhesive image.
- **Film labels and flexible packaging:** Identify BOPP, PET, PE, PP or another film; confirm treatment, primer, slip additives and end-use exposure.
- **UV varnish or laminate:** State the exact varnish or film and cure condition. Test the complete stack, not only the base stock.
- **UV adhesive:** Record adhesive grade, anilox or plate condition, laydown, lamp condition and target line speed.
- **Overprint and topcoat:** Check ink adhesion, metallic appearance and abrasion after the full finishing sequence.

If a trial includes poor adhesion, blanks, stringing or dirty edges, send photos of the defect together with substrate, adhesive, press, speed and cure details. Those details make troubleshooting faster than sending only a foil color name. Use LiangyuFoil's **foil quote requirements checklist** to prepare a complete technical request.

Cold Foil Troubleshooting Matrix

Observed issue	Likely area to check	First controlled action
Patchy transfer or blank areas	Adhesive laydown, substrate surface, foil contact or UV cure.	Inspect the adhesive image and change one process variable at a time.

Observed issue	Likely area to check	First controlled action
Stringing or dirty edges	Plate definition, adhesive rheology, foil tension or stripping geometry.	Check artwork edges, plate condition and web tension before changing foil grade.
Weak adhesion after overprint	Cure level, ink/topcoat compatibility or surface contamination.	Test adhesion after each finishing stage, not only after foil transfer.
Registration drift	Web control, plate-to-foil alignment or press setup.	Record the direction and size of drift across the run and inspect tension control.
Dull or inconsistent metallic effect	Substrate gloss, adhesive image, overprint sequence or viewing condition.	Compare approved and failed samples under the same controlled light.

How to Test a Cold Foil Sample Before Production

A press-ready sample is not necessarily a production approval. Test the final foil candidate on the final substrate, adhesive, artwork and speed range. Inspect samples from the beginning, middle and end of the run. Record the foil code, batch, substrate lot, adhesive, plate, cure condition, speed, defects and acceptance result. This creates a reference for repeat orders and helps isolate whether a later issue comes from the foil, adhesive, substrate or press condition.

1. Confirm the final substrate and all coatings, inks or laminates.
2. Run a baseline at the supplier and adhesive manufacturer’s starting conditions.
3. Change only one relevant variable per trial.
4. Inspect coverage, edge detail, registration, gloss and overprint adhesion.
5. Repeat at intended production speed and retain signed samples before bulk release.

LiangyuFoil’s **sample approval checklist** is written for hot stamping, but its core discipline is equally useful here: test the real construction, document the operating window and approve a retained standard rather than a one-off visual impression.

What to Send for a Useful Cold Foil Recommendation

A useful technical recommendation needs more than a request for “silver cold foil.” Send the material name and a sample of the final substrate, label or carton construction, the UV adhesive brand or

grade, press type, target line speed, artwork, foil coverage area, overprint or varnish sequence, target effect, estimated quantity and destination country. If a problem already exists, include sharp photographs of the defect and a sample from the start, middle and end of the run. This allows the supplier to distinguish a foil-selection question from an adhesive, substrate, cure or press-control question before a trial roll is dispatched.

Embedded media: https://www.liangyufoil.com/wp-content/uploads/2025/02/Liangyufoil.mp4

Cold foil process demonstration: adhesive imaging, foil transfer, curing and carrier rewind.

Request a Cold Foil Sample Evaluation

Submit your substrate, press type, line speed, UV adhesive, target effect, artwork and photos of any defect. LiangyuFoil can help identify the foil and sample route that should be tested before a production order.

Request a Cold Foil Sample Evaluation

FAQ

What is cold foil printing used for?

Cold foil printing is used for metallic decoration on labels, cartons, promotional sleeves and selected flexible-packaging constructions. It is especially useful when the project needs inline production, overprinted metallic colors or detailed foil imagery.

Does cold foil printing require heat?

The transfer process does not use the heated engraved die required by hot foil stamping. It uses a UV-curable adhesive and UV curing, so press, adhesive and cure conditions must be controlled for the specific job.

Can cold foil be printed over with color?

Yes, cold foil can be integrated into an overprint sequence on compatible equipment. Confirm ink, varnish, cure and adhesion performance through a complete production-condition trial.

Why is my cold foil transfer patchy?

Patchy transfer can result from adhesive laydown, surface roughness, contamination, incomplete cure, foil contact or web-tension issues. Inspect the adhesive image and run a controlled test plan rather than changing several settings at once.

What information is needed for a cold foil sample request?

Provide the substrate, coating or film details, application, press type, speed, UV adhesive, target color or effect, artwork, roll dimensions, forecast quantity, country and photos of any existing problem.